

Johnny Merehouyias

Alexandria Home Solutions

Jun 13, 2025 | 409 Photos




Detailed Window Photos

DETAILED WINDOW PHOTOS




1000-1
1100-1
1200-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt




3500-1
3600-1
3700-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt





3300-1
3400-1


Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt



500-1
600-1
700-1
800-1
900-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:04 PM
Creator: Nick Gaunt





2500-1
2600-1
2700-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



200-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt




100-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt




100-1
200-1
300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt




2400-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



2200-1
2300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:07 PM
Creator: Nick Gaunt



2000-1
2100-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

15



1700-1
1800-1
1900-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

16



1600-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

17



3900-1


Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

18




1300-1
1400-1
1500-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt



3800-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt



1500-(middle window) water damage, mold, broken seals

Project: Calvin Foster
Date: Mar 21, 2025, 12:13 PM
Creator: Nick Gaunt

21



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

22



1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

23



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

24



1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

25



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open


Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

26




1500-Mold, water damage, broken seals

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt




1500-Mold, water damage, broken seals


Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt




1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt




1200-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt



1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt




1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt




1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt




1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

43



1200-Mold, water damage, broken seals, hardware in non-functional, window does not open


Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

44




1200-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt




1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt




1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt




1100-Mold, water damage, broken seals, condensation inside of glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt




1100-Mold, water damage, broken seals, condensation inside of glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt




900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt




900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt





900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt



900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt



800-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

71




800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

72




Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt




800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt




800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt




800-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

81



Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

82




Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

85



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

86




700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



700-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

89



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

90



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt

91



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt


92



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt




600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt




600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt



600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt



500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt



500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:27 PM
Creator: Nick Gaunt




400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:27 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt




400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt




400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt





300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:31 PM
Creator: Nick Gaunt




300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt




300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt




200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt




100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt




100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt




100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt





1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt



1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt






1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt




1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt

181



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt

182




Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt

185



1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt

186




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt



3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt

197



3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:44 PM

Creator: Nick Gaunt

198




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:45 PM

Creator: Nick Gaunt




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt

211



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass



Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt


212



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt






3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt




3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt

239



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

240




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, broken glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, broken glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, broken glass



Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:49 PM
Creator: Nick Gaunt







Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt



2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt




2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt



2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt





2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt



2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:53 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:53 PM
Creator: Nick Gaunt






2400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt






2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt





2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt





2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt






2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt

337



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt

338




2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt




2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt




2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt




2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt

347



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

348




2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt




3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt




3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt




3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt



3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt






3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt




3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt

383



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

384



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

385



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

386




3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt




3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 1:03 PM
Creator: Nick Gaunt



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 1:03 PM
Creator: Nick Gaunt





3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt

393



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt

394




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:05 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:05 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt