



HISTORIC DISTRICT COMMISSION APPLICATION FOR WORK APPROVAL

City of Detroit - Planning & Development Department
2 Woodward Avenue, Suite 808
Detroit, Michigan 48226

APPLICATION ID

HDC2025-00726

PROPERTY INFORMATION

ADDRESS(ES): 19410 Canterbury Road

HISTORIC DISTRICT: Sherwood Forest

SCOPE OF WORK: (Check ALL that apply)

- | | | | | | |
|---|---|--|---|---|--------------------------------|
| ☒ Windows/
Doors | ☐ Walls/
Siding | ☐ Painting | ☐ Roof/Gutters/
Chimney | ☐ Porch/Deck/Balcony | ☐ Other |
| ☐ Demolition | ☐ Signage | ☐ New
Building | ☐ Addition | ☐ Site Improvements
(landscape, trees, fences,
patios, etc.) | |

BRIEF PROJECT DESCRIPTION:

Remove and replace approximately 39 window units.

APPLICANT IDENTIFICATION

TYPE OF APPLICANT: Contractor

NAME: Alexander Belilovsky

COMPANY NAME: Alexandria Home Solutions

ADDRESS: 24293 Telegraph Road Suite 180

CITY: Southfield

STATE: MI

ZIP: 48033

PHONE: +1 (248) 938-9866

EMAIL: johnny@alexandriawd.com

I AGREE TO AND AFFIRM THE FOLLOWING:

- ☒ I understand that the failure to upload all required documentation may result in extended review times for my project and/or a denied application.
- ☒ I understand that the review of this application by the Historic District Commission does not waive my responsibility to comply with any other applicable ordinances including obtaining appropriate permits (building, sign, etc.) or other department approvals prior to beginning the work.
- ☒ I hereby certify that the information on this application is true and correct. I certify that the proposed work is authorized by the owner of record and I have been authorized to make this application as the property owner(s) authorized agent.

Signed by:

Alexander Belilovsky

Alexandria Home Solutions

Alexander Belilovsky

11/24/2025

SIGNATURE

DATE

24293 Telegraph Road Suite 180

Southfield

MI

48033

+1 (248) 938-9866

johnny@alexandriawd.com

Questions? Contact us at hdc@detroitmi.gov or (313)224-1762

NOTE: Based on the scope of work, additional documentation may be required. See www.detroitmi.gov/hdc for scope-specific requirements.

PROJECT DETAILS – TELL US ABOUT YOUR PROJECT

Instructions: Add project details using the text box in each section. If your details exceed the space provided, attach the details via the attachment icon for that section.

ePLANS PERMIT NUMBER:

(only applicable if you've already applied for permits through ePLANS)

N/A

GENERAL

1. DESCRIPTION OF EXISTING CONDITION

Please tell us about the current appearance and conditions of the areas you want to change. You may use a few sentences or attach a separate prepared document on the right. (For example, "existing roof on my garage is covered in gray asphalt shingles in poor condition.")

Existing window frames and sashes exhibit advanced rot, water intrusion, and structural breakdown. The condition exceeds any feasible field repair. Restoration would require factory level equipment, proprietary components, and Pella certified processes that are not available outside manufacturer controlled service channels. As an authorized Pella dealer we confirm that Pella offers no repair program for units in this condition once they are outside warranty coverage. Replacement is the only viable option.



2. PHOTOGRAPHS

Help us understand your project. Please attach photographs of all areas where work is proposed.



3. DESCRIPTION OF PROJECT

In this box, tell us about what you want to do at the areas described above in box #1. (For example, Install new asphalt shingle roofing at garage.)

Remove approximately 39 existing window units that exhibit advanced rot, water intrusion, and structural failure. Install new units that match the existing style, sightlines, grille pattern, color, and operating function. Openings will be maintained at their current dimensions. Exterior trim profiles will be preserved. No changes will be made to the masonry or surrounding structure.

4. DETAILED SCOPE OF WORK

In this box, please describe all steps necessary to complete the work described in box #3. (For example, "remove existing shingles, replace wood deck as necessary, replace wood eaves, install roof vents, replace rotted fascia boards, paint, clean worksite.")

We will protect interior surfaces and remove the existing sashes, balances, hardware, and frame components while keeping all exterior brickmould intact. Remaining frame sections will be taken down to the rough framing, with fasteners and old sealants removed without disturbing the masonry or exterior casing. The rough opening will be inspected for rot, moisture damage, or structural deterioration, and any compromised wood will be replaced with matching material. The opening will be cleaned and prepared with required flashing. New full frame interior wood replacement windows will be set into the openings, shimmed, and fastened according to manufacturer specifications.

5. BROCHURES/CUT SHEETS

Please provide information on the products or materials you are proposing to install. For example, a brochure on the brand and color of the shingles proposed.




ADDITIONAL DETAILS

6. WINDOWS/DOORS Detailed photographs of window(s) and/or door(s) proposed for replacement showing the condition of the interior and exterior of the window(s) and/or door(s)	

Aluminum Clad Wood Casement Windows

Scale: 4" = 1'





Aluminum Clad Wood Casement Windows W/Jamb Extension

Scale: 4" = 1'

GLASS WIDTH = DAY LIGHT OPENING WIDTH + 1.125"
GLASS HEIGHT = DAYLIGHT OPENING HEIGHT + 1.125"

SASH WIDTH = GLASS WIDTH + 3.625"
SASH HEIGHT = GLASS HEIGHT + 3.625"


BASIC UNIT WIDTH = GLASS WIDTH + 5.1875"
BASIC UNIT HEIGHT = GLASS HEIGHT + 5.1875"




Aluminum Clad Wood Casement

Scale: 4" = 1'


Tight Mull Details




 **MULL DETAIL**
CLAD OPERATING, LEFT/PICTURE



 **MULL DETAIL**
CLAD PICTURE/OPERATING, RIGHT



 **MULL DETAIL**
CLAD PICTURE/PICTURE




 **MULL DETAIL**
CLAD OPERTING/OPERATING

Aluminum Clad Wood Casement


Scale: 4" = 1'

Spread Mull Details




EXTERIOR

1" SOLID SPREAD MULL
CLAD PICTURE/OPERATING



EXTERIOR

2" SOLID SPREAD MULL
CLAD PICTURE/OPERATING




EXTERIOR

4" INSULATED BOX SPREAD MULL
CLAD PICTURE/OPERATING

Aluminum Clad Wood Casement

Scale: 4" = 1'

Spread Mull Details




MULL DEFINITIONS

- **INSULATED BOX MULLS** AVAILABLE FOR 4" & 6" MULLS ONLY

THESE RUN FULL UNIT HEIGHT & ARE PERMANENTLY ATTACHED

- **SOLID MULLS** CONSIST OF SINGLE OR MULTIPLE PIECES OF FINGER JOINT WOOD PERMANENTLY ATTACHED TOGETHER AT THE SIZES SHOWN - THESE RUN FULL UNIT HEIGHT & ARE PERMANENTLY ATTACHED


- **HOLLOW MULLS** ARE CONSTRUCTED WITH 6" WOOD STRIPS, AS SHOWN, TEMPORARILY ATTACHED TO THE UNITS NEAR THE TOP & BOTTOM UP TO 60" UNIT HEIGHTS -
- UNITS THAT EXCEED A 60" HEIGHT MAY HAVE 4 OR MORE WOOD PIECES APPLIED
- THESE TEMPORARY PIECES ARE FOR FIELD REMOVAL PRIOR TO UNIT INSTALLATION




Aluminum Clad Wood Casement

Scale: 4" = 1'

Spread Mull Details



1/4 inch Aluminum Plate Mull



19410 Canterbury Road

Window Locations

Window Numbering Information:

To ensure absolute clarity and prevent any potential misinterpretation, we have included a reference chart aligning the window schedule line numbers with the corresponding labels shown on the elevation photos.

In our window schedule, each item is numbered in increments of 100 (e.g., 100, 200, 300), a common formatting choice that provides space for potential future additions or edits.

For the elevation images, we used a simplified numerical system (1, 2, 3, etc.) to maintain visual clarity and avoid crowding the drawings with redundant zeroes.

While the numerical correlation between the two formats is direct and consistent, each schedule item corresponds to its matching sequential photo label, we understand that providing an explicit conversion table may assist in reinforcing this relationship.

The chart on the next slide outlines this one-to-one mapping in full detail.

We hope this resolves any remaining ambiguity.

Window Numbering Reference Chart

Window Schedule 100 = Photo Label 1	Window Schedule 2100 = Photo Label 21
Window Schedule 200 = Photo Label 2	Window Schedule 2200 = Photo Label 22
Window Schedule 300 = Photo Label 3	Window Schedule 2300 = Photo Label 23
Window Schedule 400 = Photo Label 4	Window Schedule 2400 = Photo Label 24
Window Schedule 500 = Photo Label 5	Window Schedule 2500 = Photo Label 25
Window Schedule 600 = Photo Label 6	Window Schedule 2600 = Photo Label 26
Window Schedule 700 = Photo Label 7	Window Schedule 2700 = Photo Label 27
Window Schedule 800 = Photo Label 8	Window Schedule 2800 = Photo Label 28
Window Schedule 900 = Photo Label 9	Window Schedule 2900 = Photo Label 29
Window Schedule 1000 = Photo Label 10	Window Schedule 3000 = Photo Label 30
Window Schedule 1100 = Photo Label 11	Window Schedule 3100 = Photo Label 31
Window Schedule 1200 = Photo Label 12	Window Schedule 3200 = Photo Label 32
Window Schedule 1300 = Photo Label 13	Window Schedule 3300 = Photo Label 33
Window Schedule 1400 = Photo Label 14	Window Schedule 3400 = Photo Label 34
Window Schedule 1500 = Photo Label 15	Window Schedule 3500 = Photo Label 35
Window Schedule 1600 = Photo Label 16	Window Schedule 3600 = Photo Label 36
Window Schedule 1700 = Photo Label 17	Window Schedule 3700 = Photo Label 37
Window Schedule 1800 = Photo Label 18	Window Schedule 3800 = Photo Label 38
Window Schedule 1900 = Photo Label 19	Window Schedule 3900 = Photo Label 39
Window Schedule 2000 = Photo Label 20	

FRONT



RIGHT



BACK



Johnny Merehouyias

Alexandria Home Solutions

Jun 13, 2025 | 409 Photos



Detailed Window Photos

DETAILED WINDOW PHOTOS

1



1000-1
1100-1
1200-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt

2



3500-1
3600-1
3700-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt




3300-1
3400-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:03 PM
Creator: Nick Gaunt




500-1
600-1
700-1
800-1
900-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:04 PM
Creator: Nick Gaunt



2800-1
2900-1
3000-1
3100-1
3200-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:04 PM
Creator: Nick Gaunt



400-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:05 PM
Creator: Nick Gaunt



2500-1
2600-1
2700-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt




200-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt




100-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



100-1
200-1
300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



2400-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:06 PM
Creator: Nick Gaunt



2200-1
2300-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:07 PM
Creator: Nick Gaunt



2000-1
2100-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

15



1700-1
1800-1
1900-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

16



1600-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

17



3900-1


Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt

18




1300-1
1400-1
1500-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt



3800-1

Project: Calvin Foster
Date: Mar 21, 2025, 12:08 PM
Creator: Nick Gaunt



1500-(middle window) water damage, mold, broken seals

Project: Calvin Foster
Date: Mar 21, 2025, 12:13 PM
Creator: Nick Gaunt

21



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster

Date: Mar 21, 2025, 12:14 PM

Creator: Nick Gaunt

22



1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster

Date: Mar 21, 2025, 12:14 PM

Creator: Nick Gaunt

23



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

24



1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:14 PM
Creator: Nick Gaunt

25



1300-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

26



1500-Mold, water damage, broken seals

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

27



1500-Mold, water damage, broken seals

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

28



Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

29




Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

30




1400-Mold and water damage, broken seals, hardware in nonfunctional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:15 PM
Creator: Nick Gaunt

33




Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt


34



Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt



1200-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt

37



1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt

38




1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:16 PM
Creator: Nick Gaunt



1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt



1000-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

41



Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

42



Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

43



1200-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

44



1200-Mold, water damage, broken seals, hardware in non-functional, window does not open

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

45



1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:17 PM
Creator: Nick Gaunt

46




1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt



1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:18 PM
Creator: Nick Gaunt





53





Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt



54






1100-Mold, water damage, broken seals, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:19 PM
Creator: Nick Gaunt










Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:20 PM
Creator: Nick Gaunt

63



900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:20 PM

Creator: Nick Gaunt

64



900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:20 PM

Creator: Nick Gaunt

65



900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:20 PM

Creator: Nick Gaunt

66



900-Mold, water damage, broken seals, hardware in non-functional, window does not open, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:21 PM

Creator: Nick Gaunt

67



Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

68



Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

69



Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

70



800-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

71



800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

72



Project: Calvin Foster
Date: Mar 21, 2025, 12:21 PM
Creator: Nick Gaunt

73



800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

74



800-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

75



Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

76



800-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

77




Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

78



Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt



81



Project: Calvin Foster
Date: Mar 21, 2025, 12:22 PM
Creator: Nick Gaunt

82



Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

83



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

84



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

85



700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

86




700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt



700-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

89





700-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:23 PM
Creator: Nick Gaunt

90



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt





95



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt

96



600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt

97



Project: Calvin Foster
Date: Mar 21, 2025, 12:24 PM
Creator: Nick Gaunt

98



600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt




600-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:25 PM
Creator: Nick Gaunt



500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt

107



Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt

108



500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt

109




Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt

110




500-Mold, water damage, broken seals, decayed wood inside of glass, non functioning hardware, window does not open, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:26 PM
Creator: Nick Gaunt



113



Project: Calvin Foster
Date: Mar 21, 2025, 12:27 PM
Creator: Nick Gaunt

114



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:27 PM
Creator: Nick Gaunt

115



400-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt

116



Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:28 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:29 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt

127



Project: Calvin Foster

Date: Mar 21, 2025, 12:30 PM

Creator: Nick Gaunt

128



400-Mold, water damage, broken seals, decayed wood inside of glass, condensation inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:30 PM

Creator: Nick Gaunt

129



Project: Calvin Foster

Date: Mar 21, 2025, 12:30 PM

Creator: Nick Gaunt

130



400-Mold, water damage, broken seals, decayed wood
inside of glass, condensation inside of glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:30 PM

Creator: Nick Gaunt

131




Project: Calvin Foster
Date: Mar 21, 2025, 12:30 PM
Creator: Nick Gaunt

132



Project: Calvin Foster
Date: Mar 21, 2025, 12:31 PM
Creator: Nick Gaunt



300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:31 PM
Creator: Nick Gaunt




300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt




300- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt

137




Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt

138



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:32 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt



200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt




200- Broken frame, cracked seals, water damage, mold, decayed wood inside of glass, condensation in between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:33 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:34 PM
Creator: Nick Gaunt



100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt



100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt

151



100- window is not sealed properly, water leaks, would like to replace with wood to restore the historical look of the house

Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt

152



Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt

153



Project: Calvin Foster
Date: Mar 21, 2025, 12:35 PM
Creator: Nick Gaunt

154



Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt

155



1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:38 PM

Creator: Nick Gaunt

156



1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:38 PM

Creator: Nick Gaunt

157




Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt

158




1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt




1600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:38 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt






Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:39 PM
Creator: Nick Gaunt



1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt

169





Project: Calvin Foster
Date: Mar 21, 2025, 12:41 PM
Creator: Nick Gaunt

170



1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt



173





1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt

174




Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt





1700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:42 PM
Creator: Nick Gaunt

179



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt

180



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt

181



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt


182



Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



1800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass



Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt

185



1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt

186



1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:43 PM

Creator: Nick Gaunt




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt



1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt




1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt




Project: Calvin Foster
Date: Mar 21, 2025, 12:43 PM
Creator: Nick Gaunt






1900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:44 PM
Creator: Nick Gaunt

195



Project: Calvin Foster

Date: Mar 21, 2025, 12:44 PM

Creator: Nick Gaunt

196



3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:44 PM

Creator: Nick Gaunt

197



3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:44 PM

Creator: Nick Gaunt

198




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:45 PM

Creator: Nick Gaunt





3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt




3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt








Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt



3900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:45 PM
Creator: Nick Gaunt





209



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:45 PM

Creator: Nick Gaunt

210




3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:46 PM

Creator: Nick Gaunt





3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt



3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt







3800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:46 PM
Creator: Nick Gaunt



219



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:46 PM

Creator: Nick Gaunt

220



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:47 PM

Creator: Nick Gaunt

221



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:47 PM

Creator: Nick Gaunt

222




3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:47 PM

Creator: Nick Gaunt



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt

225



3700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:47 PM

Creator: Nick Gaunt



226




Project: Calvin Foster


Date: Mar 21, 2025, 12:47 PM

Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:47 PM
Creator: Nick Gaunt

231



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

232



Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

233



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

234



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

235



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt

236



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:48 PM
Creator: Nick Gaunt

239



3600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

240



3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

241



3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, broken glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:48 PM

Creator: Nick Gaunt

242



3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, broken glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:49 PM

Creator: Nick Gaunt

243



3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:49 PM

Creator: Nick Gaunt

244







3500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster



Date: Mar 21, 2025, 12:49 PM

Creator: Nick Gaunt









253



Project: Calvin Foster

Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt

254



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt

255



2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt

256




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt



2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt

259



2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt

260




2000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:50 PM

Creator: Nick Gaunt



263



2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt

264



Project: Calvin Foster
Date: Mar 21, 2025, 12:50 PM
Creator: Nick Gaunt

265



2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:51 PM

Creator: Nick Gaunt

266



2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:51 PM

Creator: Nick Gaunt





2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt



2100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt



271



Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt

272



2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt

273




Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt

274



2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass, bugs between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:51 PM
Creator: Nick Gaunt



277



2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:52 PM

Creator: Nick Gaunt

278






2200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:52 PM

Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt



2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt

283



2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:52 PM

Creator: Nick Gaunt

284



Project: Calvin Foster


Date: Mar 21, 2025, 12:52 PM

Creator: Nick Gaunt



2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt







2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:52 PM
Creator: Nick Gaunt





293



2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:54 PM

Creator: Nick Gaunt

294



Project: Calvin Foster


Date: Mar 21, 2025, 12:54 PM

Creator: Nick Gaunt




2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt



2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt





2300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:54 PM
Creator: Nick Gaunt



301



2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt

302



2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt

303



2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt

304



2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt

305



2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt

306






2500- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:55 PM

Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:55 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt

311



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt

312




2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt

315



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt

316



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt





2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



2600- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:56 PM
Creator: Nick Gaunt



321



2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt

322



2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt

323



2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt


324



Project: Calvin Foster


Date: Mar 21, 2025, 12:56 PM

Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt




2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt





2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass



Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt



2700- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:57 PM
Creator: Nick Gaunt





333



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:57 PM

Creator: Nick Gaunt

334



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:57 PM

Creator: Nick Gaunt

335



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt

336



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt

337



2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt

338




2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt




2900- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:58 PM
Creator: Nick Gaunt



343



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:58 PM

Creator: Nick Gaunt

344



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

345



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

346



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

347



2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt


348




2800- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt

353



3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

354



3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 12:59 PM

Creator: Nick Gaunt

355





Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt

356



3000- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 12:59 PM
Creator: Nick Gaunt





3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt



3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt

361



3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:00 PM

Creator: Nick Gaunt

362




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 1:00 PM

Creator: Nick Gaunt



3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt




3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt



3100- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt

367



Project: Calvin Foster
Date: Mar 21, 2025, 1:00 PM
Creator: Nick Gaunt

368



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt

369



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:01 PM

Creator: Nick Gaunt

370




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:01 PM

Creator: Nick Gaunt



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt

373



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:01 PM

Creator: Nick Gaunt

374



3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:01 PM

Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt




3200- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:01 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt

379




Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt

380




3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:02 PM
Creator: Nick Gaunt

383



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

384



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

385



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

386



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

387




3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

388



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:03 PM

Creator: Nick Gaunt

389



Project: Calvin Foster
Date: Mar 21, 2025, 1:03 PM
Creator: Nick Gaunt

390



3300- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:03 PM
Creator: Nick Gaunt

391



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt

392



Project: Calvin Foster

Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt

393



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt

394




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt

397



3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster

Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt

398




3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass

Project: Calvin Foster


Date: Mar 21, 2025, 1:04 PM

Creator: Nick Gaunt






3400- water damage, mold, broken seals, hardware is non functioning, window does not open, condensation between glass, decayed wood between glass


Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt





Project: Calvin Foster
Date: Mar 21, 2025, 1:04 PM
Creator: Nick Gaunt











Project: Calvin Foster
Date: Mar 21, 2025, 1:06 PM
Creator: Nick Gaunt

ESTIMATE

**Prepared For**

R- Calvin Foster
19410 Canterbury
Detroit, MI 48221
(608) 575-8638

Windows Diverse Services

3700 E. 8 Mile Rd.
Detroit, MI 48234
Phone: (313) 655-5684
Email: windowsdiverseservices@gmail.com
Web: www.windowssds.com

Estimate # 11683
Date 09/17/2025
PO # 26EC91

Description**WINDOW NEEDS ASSESSMENT | WNA****\$0.00****WINDOW NEEDS ASSESSMENT | WNA**

Dear [Commission Contact],
I am writing regarding the Pella windows under review for [property/project name]. After evaluating the scope of work and requirements, we must clarify that our company cannot undertake restoration of these Pella units.

Pella windows are factory-engineered products that require a specialized wood shop, manufacturer-specific parts, and detailed technical knowledge of their internal anatomy. Their restoration work can only be completed properly by a trained Pella technician with access to the manufacturer's equipment and standards. This falls outside the services we provide.

Our team specializes in servicing and restoring traditional wood windows, but not factory replacement lines such as Pella.

In this case, the correct path forward is replacement with new Pella units rather than attempting restoration. For accuracy and long-term performance, restoration of existing Pella windows is not feasible without manufacturer involvement.

Please let this serve as a clear record that we do not restore replacement windows, including Pella. Replacement with new Pella products is the appropriate and practical option available.

Thank you for your understanding. Please feel free to contact me if you require any additional information.
Sincerely,

SCOPE OF WORK SUMMARY		\$0.00
SCOPE OF WORK SUMMARY		
« SERVICE REQUEST FULL RESTORATION.		
SHOP: Remove all lead-based/old paint and putty, sand smooth, repair wood damage, restore weatherstripping, restore stops all, mechanical restoration of sash ropes and pulleys, restore profiles (muntins & mullions), restore window sill, clean glass, and replace broken glass, bed glass in new putty, putty glaze, prime and paint or stain. Restore hardware pulleys, locks and handles or install new locks and handles.		
26 SINGLE WOOD SASH CASEMENT WINDOWS		
PELLA WOOD CLAD CASEMENT		
With 91 total lites. 26EC91		

Subtotal	\$0.00
Total	\$0.00


Notes:

9/17/25: Wednesday. Met with customer to discuss restoration of wood clad Pella windows from the 1950s

THANK YOU ||
Visit us Online at www.WindowsDS.com to learn more about our journey.

















ACCEPTANCE OF PROPOSAL

All material is guaranteed to be as specified.

All work is to be compiled in a substantial workmanlike manner according to specifications submitted, per standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders and will become an extra charge over and above the estimate. All agreements are contingent upon strikes, accidents, or delays beyond our control. Owner to carry fire, tornado, and other necessary insurance.

Our workers are fully covered by Workmen's Compensation insurance.

By signing this estimate the client has accepted the proposal and, if applicable, terms of the working agreement. Submitting a deposit is not only a financial transaction, but also serves as an agreement within the terms of our contract. Your deposit signifies your commitment to the terms and conditions outlined in the agreement.

ACCEPTANCE OF PROPOSAL

The above prices, specifications, and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.

Date of Acceptance:

Authorized <

ESTIMATE

**Prepared For**

R- Calvin Foster
 19410 Canterbury
 Detroit, MI 48221
 (608) 575-8638

Windows Diverse Services

3700 E. 8 Mile Rd.
 Detroit, MI 48234
 Phone: (313) 655-5684
 Email: windowsdiverseservices@gmail.com
 Web: www.windowssds.com

Estimate # 11683
 Date 09/17/2025
 PO # 26EC91

Description**WINDOW NEEDS ASSESSMENT | WNA****\$0.00****WINDOW NEEDS ASSESSMENT | WNA**

Dear [Commission Contact],
 I am writing regarding the Pella windows under review for [property/project name]. After evaluating the scope of work and requirements, we must clarify that our company cannot undertake restoration of these Pella units.

Pella windows are factory-engineered products that require a specialized wood shop, manufacturer-specific parts, and detailed technical knowledge of their internal anatomy. Their restoration work can only be completed properly by a trained Pella technician with access to the manufacturer's equipment and standards. This falls outside the services we provide.

Our team specializes in servicing and restoring traditional wood windows, but not factory replacement lines such as Pella.

In this case, the correct path forward is replacement with new Pella units rather than attempting restoration. For accuracy and long-term performance, restoration of existing Pella windows is not feasible without manufacturer involvement.

Please let this serve as a clear record that we do not restore replacement windows, including Pella. Replacement with new Pella products is the appropriate and practical option available.

Thank you for your understanding. Please feel free to contact me if you require any additional information.
 Sincerely,

SCOPE OF WORK SUMMARY		\$0.00
SCOPE OF WORK SUMMARY		
« SERVICE REQUEST FULL RESTORATION.		
SHOP: Remove all lead-based/old paint and putty, sand smooth, repair wood damage, restore weatherstripping, restore stops all, mechanical restoration of sash ropes and pulleys, restore profiles (muntins & mullions), restore window sill, clean glass, and replace broken glass, bed glass in new putty, putty glaze, prime and paint or stain. Restore hardware pulleys, locks and handles or install new locks and handles.		
26 SINGLE WOOD SASH CASEMENT WINDOWS		
PELLA WOOD CLAD CASEMENT		
With 91 total lites. 26EC91		

Subtotal	\$0.00
Total	\$0.00


Notes:

9/17/25: Wednesday. Met with customer to discuss restoration of wood clad Pella windows from the 1950s

THANK YOU ||
Visit us Online at www.WindowsDS.com to learn more about our journey.

















ACCEPTANCE OF PROPOSAL

All material is guaranteed to be as specified.

All work is to be compiled in a substantial workmanlike manner according to specifications submitted, per standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders and will become an extra charge over and above the estimate. All agreements are contingent upon strikes, accidents, or delays beyond our control. Owner to carry fire, tornado, and other necessary insurance.

Our workers are fully covered by Workmen's Compensation insurance.

By signing this estimate the client has accepted the proposal and, if applicable, terms of the working agreement. Submitting a deposit is not only a financial transaction, but also serves as an agreement within the terms of our contract. Your deposit signifies your commitment to the terms and conditions outlined in the agreement.

ACCEPTANCE OF PROPOSAL

The above prices, specifications, and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.

Date of Acceptance:

Authorized <